

Dimex P60AD Outward Window

Glass Configuration

Table1

Glazing Bead	Gasket650500	Gasket650400	Gasket650300	Remark
620200	4mm Glass	5mm Glass	6mm Glass	
621100	18mm Glass	19mm Glass	20mm Glass	
620100	20mm Glass	21mm Glass	22mm Glass	The same as 320100
625300	23mm Glass	24mm Glass	25mm Glass	The same as 325300
620400	27mm Glass	28mm Glass	29mm Glass	
621600	31mm Glass	32mm Glass	33mm Glass	
620300	32mm Glass	33mm Glass	34mm Glass	

Accessories


Table3

No.	Name & Art. No.	Remark
1	Glazing Wedge 1mm D006	
2	Glazing Wedge 2mm D007	
3	Glazing Wedge 3mm D008	
4	Glazing Wedge 4mm D009	
5	Glazing Wedge 5mm D010	
6	Gasket 650100	
7	Glazing Bridge 630100	


Assembly Parts

Table2

No.	Name & Art. No.	Remark
①	60 Casement Window Frame 310100-JL-B	
②	60 Outward Window Sash 310300-JL-A	
③	60 Mullion 310400-JL-B	
④	Glazing Bead 320100	The Glazing Beads in Table1 are Optional
⑤	Reinforcement 360100	
⑥	Reinforcement 360300	
⑦	Reinforcement 360400	



Vertical
Assembly
Drawing



Horizontal Assembly Drawing

Version:12-3/15

Tel: +86 512 53563 223/227

Peony Series

Fax: +86 512 53563201

<http://www.dimex.com.cn>

e-mail: export@dimex.com.cn

Window Assembly Drawing 4